

Return test levels continued.

Bench	Back Sights	Invert	Fore Sights	Page	Dam	Remarks
				61.138		
	11.195	72.333				
			0.425	71.908		
	10.919	82.827				
			1.144	81.683		
	10.367	92.050				
			0.608	91.442		
	8.848	100.290				
89.962			10.328			Top surface of foundation at S.W. corner of Rock River Paper Company's smoke stack.
			6.199	94.091		
	4.235	98.326				
			5.822	92.504		
	11.230	103.734				
103.264			0.470			Top surface of water table at S.E. corner of North College Building.
102.166			1.568			Top surface of water table at S.E. corner of Middle College Building.
	0.207	102.373				
100.006			2.367			Top surface of water table Memorial Hall

Averaging the two sets of levels I find as follows:

The present top surface of the dam is below the top surface of the water table of Memorial Hall at the place indicated in the notes. 49.45

The present top surface of the dam is below the top surface of the water table at the South East corner of the Middle College Building. 51.18

The present top surface of the dam is below the top surface of the water table at the South East corner of the North College Building. 52.42

HOYEVNUS VTLAOS
COUNTY SURVEYOR
1859-1906

COUNTY SURVEYOR
RECORD 1859-1906