

Corner Established by
Self. See Book One
Page 107

Drove plate. Lost
had board alone on
the south side of
the - bulker in line
to corner

Corner Established by
Self. See Book One
Page 107



Drove plate and surrounded
it with 3 hard head pins

Corner Established by
Self. See Book One Page 107

Corner Established by Self.
See Book One Page 107

Center of

Section

Corner Established by Self. See
Book One Page 107

The above is a record and plot of a
survey made by me on the N. E. 1/4 of the N. W. 1/4
of Section 22 Jamesville part of May 21 &
22 - 1894

Edward Rieger, County Surveyor