PLAT AND RECORD

Of a Survey on Section 17/8 T 3 R 13 E. of the 4 P. M. in Harmony Township

Rock County, Wisconsin, made ..... the 19

I hereby certify that the following is a correct record of said survey as made by me.

COUNTY BUILDING
IN CITY OF BELOIT

..... County Surveyor.



This Record is incomplete
See P. 241 of this book.
(Signed) Edward Ruger, County Surveyor.

Copied from P. 235 Vol. 2 Original County Surveyor's Record.