


PLAT AND RECORD

287
VOL. 5

Of a Survey on Section 26 T 4 R 12 E. of the 4 P. M. in FULTON Township
Rock County, Wisconsin, made MAY the 4 1977

I hereby certify that the following is a correct record of said survey as made by me
**COUNTY BUILDING
CITY OF JANESVILLE**

Ronald Barnes
County Surveyor.



There is a problem with the center of section 26. Mr. Clayton Shimeall supposedly set the center at the intersection of the E/W $\frac{1}{4}$ line and N/S $\frac{1}{4}$ line. Since then many surveys by Mr. Shimeall and other surveyors have been tied to this point. I was requested to verify the location of the E $\frac{1}{4}$ corner and the center. I traversed the section and tied into the E $\frac{1}{4}$, W $\frac{1}{4}$, S $\frac{1}{4}$, N $\frac{1}{4}$, SE corners and the center of section as set by Mr. Shimeall. The computed distances to the E $\frac{1}{4}$ corner as noted in surveys done by Mr. Shimeall and Hugh Lee indicates they used the same corner. The N $\frac{1}{4}$ corner agrees with the short ties that Mr. Shimeall had on a plat of survey. My computations show that the intersection of the E/W and N/S $\frac{1}{4}$ line is as recorded by Mr. Hugh Lee on the plat of survey dated Oct 30, 1972.

MICROFILMED