

# VOL. 5 PLAT AND RECORD

Of a Survey on Section 22,24,30 1 14 CLINTON  
28 T 3 R 13 E. of the 4 P. M. in Harmony Township  
 Rock County, Wisconsin, made September the 27  
28 1977

I hereby certify that the following is a correct record of said survey as made by me.

COUNTY BUILDING  
 CITY OF JANESVILLE



NE corner sec. 28 T3N R13E  
 found mon. box 0.3' deep removed box and found  
 gas pipe 2' deep. Set alum. monument.

N1/4 corner sec. 28 T3N R13E  
 Found mon. box 0.3' deep.  
 set alum. mon. inside mon. box  
 FD. 1" I.P. & STONE

N 1/4 COR. SEC. 22 T.1N. R.14E  
 FD. PK and SET ALUM. MON.

CENTER SEC. 22 T.1N. R.14E  
 FD. RR SPIKE and SET ALUM. MON.

S 1/4 COR. SEC. 24 T.1N. R.14E.  
 FD. CONC. NAIL and SET ALUM. MON.

SW COR. SEC. 30 T.1N. R.14E  
 FD. ALUM. MON. and PUT 4" RISER ON MON

MICROFILMED