

# PLAT AND RECORD


185

VOL. 6


Of a Survey on Section 14, 15 T. 3 R. 13 E. of the 4 P. in HARMONY Township  
Rock County, Wisconsin, made AUG 19 81

I hereby certify that the following is a correct record of said survey made by me.


COUNTY BUILDING  
CITY OF JANESVILLE



County Surveyor.



MICROFILMED



6" NORWAY PINE FOUND CUT LIMESTONE ABOUT 1' UNDER PAVEMENT. REPLACED STONE WITH ALUM MON

W 1/4 COR SEC 14

28" MAPLE 3/8" X 32" IRON BOLT

SW COR SEC 14